



**CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY**

Jaro, Iloilo City
Tel. Nos. (033) 3291971 (to 79) local 1085



**DOH Accreditation No.03
Valid until 12/31/2016**

"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Address: Brgy Dolores, Dumalag, Capiz
Sample Source: Treated Water
Location: Faucet
Accession No: 15-377

Date/Time Collection: 01/20/15; 3:20AM
Date of Examination: 01/20/15
Date Reported: 01/22/15
Date Release: 01/26/15
Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Clear, No sediments

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AG 2006-0024	< 1.1	< 1.1	< 500	

Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 20th
Ed. 1998

NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Mrs. Irene D. Salonga, RMI
DOH/NRL Cert # WMLA-10-0119

Certified Correct:

Dr. Dalmia H. Pescos, RChE.
Head, CPU Water Laboratory



**CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY**

Jaro, Iloilo City
Tel. Nos. (033) 3291971 (to 79) local 1085



**DOH Accreditation No.03
Valid until 12/31/2016**

"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Sitio Ayuyan,

Date/Time Collection: 01/20/15; 3:20AM

Address: Brgy Sto. Angel, Dumalag, Capiz Date of Examination: 01/20/15

Sample Source: Treated Water Date Reported: 01/22/15

Location: Faucet Date Release: 01/26/15

Accession No: 15-376 Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Clear, No sediments

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	

Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 20th
Ed. 1998

NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Mrs. Irene D. Salonga, RMT
DOH/NRL Cert # WMLA-10-0119

Certified Correct:

Dr. Danlita H. Pescos, RChE.
Head, CPU Water Laboratory



CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY

Jaro, Iloilo City
Tel. Nos. (033) 3291971 (to 79) local 1085



DOH Accreditation No.03
Valid until 12/31/2016

"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Sitio, Ayuya, Sto. Angel,

Address: Dumalag, Capiz,

Sample Source: Treated Water

Location: Faucet (Spring)

Accession No: 15-810

Date/Time Collection: 02/17/15; 5:30 AM

Date of Examination: 02/17/15

Date Reported: 02/19/15

Date Release: 02/23/15

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Cloudy, with fresh chlorine


Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	

Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 20th
Ed. 1998


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:


Mrs. Irene D. Salonga RMT
DOH/NRL Cert # WMLA-10-0119


Certified Correct:


Dr. Danila H. Pescos, RChE
Head, CPU Water Laboratory



CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY

Jaro, Iloilo City
Tel. Nos. (033) 3291971 (to 79) local 1085



DOH Accreditation No.03
Valid until 12/31/2016

"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Date/Time Collection: 02/17/15; 5:00 AM

Address: Dolores, Dumalag, Capiz,

Date of Examination: 02/17/15

Sample Source: Treated Water

Date Reported: 02/19/15

Location: Reservoir (Spring)

Date Release: 02/23/15

Accession No: 15-809

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Cloudy, with fresh chlorine

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	

Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 20th
Ed. 1998

NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Irene D. Salonga
Mrs. Irene D. Salonga RMT
DOH/NRL Cert # WMLA-10-0119

Certified Correct:

Dahlia H. Pescos
Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory

**CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY**

Jaro, Iloilo City

Tel. Nos. (033) 3291971 (to 79) local 1085



**DOH Accreditation No.03
Valid until 12/31/2016**

“TEST REPORT”

Requesting Party/Client: Dumalag Water District

Sitio Ayuyan,

Date/Time Collection: 03/24/15; 6:30 AM

Address: Brgy Sto. Angel, Dumalag, Capiz Date of Examination: 03/24/15

Sample Source: Treated Water

Date Reported: 03/26/15

Location: Faucet

Date Release: 03/31/15

Accession No: 15-1314

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Cloudy with fresh chlorine

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	


Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 20th
Ed. 1998


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Certified Correct:


Mrs. Irene D. Salonga, RMT
DOH/NRL Cert # WMLA-10-0119


Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory

**CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY**

Jaro, Iloilo City

Tel. Nos. (033) 3291971 (to 79) local 1085



DOH Accreditation No.03

Valid until 12/31/2016



"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Address: Brgy Dolores Dumalag, Capiz

Sample Source: Treated Water

Location: Faucet

Accession No: 15-1315

Date/Time Collection: 03/24/15; 6:00 AM

Date of Examination: 03/24/15

Date Reported: 03/26/15

Date Release: 03/31/15

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Cloudy with fresh chlorine


Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	

Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 20th
Ed. 1998


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:


Mrs. Irene D. Salonga RMT
DOH/NRL Cert # WMLA-10-0119

Certified Correct:


Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory



CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY

Jaro, Iloilo City
Tel. Nos. (033) 3291971 (to 79) local 1085

DOH Accreditation No.03
Valid until 12/31/2016



"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Address: Brgy. Sto. Angel, Dumalag, Capiz

Sample Source: Treated Water

Location: Faucet

Accession No: 15-1460

Date/Time Collection 04/14/15; 6:30 AM

Date of Examination: 04/14/15

Date Reported: 04/16/15

Date Release: 04/20/15

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Cloudy, with fresh chlorine

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	


Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 20th
Ed. 1998


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Certified Correct:


Mrs. Irene D. Salonga RMT
DOH/NRL Cert # WMLA-10-0119


Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory

CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY

Jaro, Iloilo City

Tel. Nos. (033) 3291971 (to 79) local 1085



DOH Accreditation No.03
Valid until 12/31/2016

"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Address: Brgy. Dolores, Dumalag, Capiz

Sample Source: Treated Water

Location: Faucet

Accession No: 15-1459

Date/Time Collection 04/14/15; 6:00 AM

Date of Examination: 04/14/15

Date Reported: 04/16/15

Date Release: 04/20/15

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Clear, No sediments

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	


Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 20th
Ed. 1998


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Certified Correct:


Mrs. Irene D. Salonga, RMT
DOH/NRL Cert # WMLA-10-0119


Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory



CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY

Jaro, Iloilo City
Tel. Nos. (033) 3291971 (to 79) local 1085

DOH Accreditation No.03
Valid until 12/31/2016



"TEST REPORT"

Requesting Party/Client: Dumalag Water District
Sitio Ayuyan,
Address: Brgy. Sto. Angel, Dumalag, Capiz
Sample Source: Treated Water
Location: Faucet
Accession No: 15-1894

Date/Time Collection: 05/19/15; 6:30 AM
Date of Examination: 05/19/15
Date Reported: 05/21/15
Date Release: 05/25/15
Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Clear, No sediments

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	


Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 22nd Ed. 2012


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Certified Correct:


Mrs. Irene D. Salonga, RMT
DOH/NRL Cert # WMLA-10-0119


Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory

CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY

Jaro, Iloilo City

Tel. Nos. (033) 3291971 (to 79) local 1085



DOH Accreditation No.03
Valid until 12/31/2016

"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Address: Brgy. Dolores, Dumalag, Capiz

Sample Source: Treated Water

Location: Faucet

Accession No: 15-1893

Date/Time Collection: 05/19/15; 6:00 AM

Date of Examination: 05/19/15

Date Reported: 05/21/15

Date Release: 05/25/15

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Clear, No sediments

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	


Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 22nd Ed. 2012


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Certified Correct:


Mrs. Irene D. Salonga, RMT
DOH/NRL Cert # WMLA-10-0119


Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory


CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY

Jaro, Iloilo City

Tel. Nos. (033) 3291971 (to 79) local 1085

DOH Accreditation No.03

Valid until 12/31/2016



"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Address: Brgy Dolores, Dumalag, Capiz

Sample Source: Treated Water

Location: Faucet

Accession No: 15-2221

Date/Time Collection: 06/16/15; 5:30 AM

Date of Examination: 06/16/15

Date Reported: 06/18/15

Date Release: 06/22/15

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Clear, No sediments

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	


Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 22nd Ed. 2012


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Certified Correct:


Mrs. Irene D. Salonga, RMT
DOH/NRL Cert # WMLA-10-0119


Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory

**CENTRAL PHILIPPINE UNIVERSITY
WATER ANALYSIS LABORATORY**

Jaro, Iloilo City

Tel. Nos. (033) 3291971 (to 79) local 1085



**DOH Accreditation No.03
Valid until 12/31/2016**

"TEST REPORT"

Requesting Party/Client: Dumalag Water District

Sitio Ayuyan,

Address: Brgy Sto Angel, Dumalag, Capiz

Sample Source: Treated Water

Location: Faucet

Accession No: 15-2222

Date/Time Collection: 06/16/15; 6:00 AM

Date of Examination: 06/16/15

Date Reported: 06/18/15

Date Release: 06/22/15

Receipt:

BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE

Physical characteristics: Clear, No sediments

Sample Code	Results of Analysis*			Remarks
	Total Coliform (MPN/100ml)	Fecal Coliform (MPN/100 ml)	HPC (CFU/ml)	
	< 1.1	< 1.1	0	PASSED
PNSDW 2007 AO 2006-0024	< 1.1	< 1.1	< 500	


Legend: Test Method Used = Multiple Tube Fermentation Techniques, SMEW 22nd Ed. 2012


NOTE :

- Result of examination specifically related to samples received.
- Test results shall not be reproduced except in full without the written approval of the examining laboratory.

Analyst:

Certified Correct:


Mrs. Irene D. Salonga, RMT
DOH/NRL Cert # WMLA-10-0119


Dr. Dahlia H. Pescos, RChE.
Head, CPU Water Laboratory



Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.
Accreditation Number: 06-051-14-LW-2
Jalandoni Estate, Lapuz Iloilo City
email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15718

Name of Customer: **DUMALAG WATER DISTRICT**

Address: Sitio Ayuyan Brgy. Sto Niño, Dumalag, Capiz

Sample Description: Clear / Without Sediment Date Sample Submitted: July 23, 2015

Time of Sampling: 08:16 PM Date Sample Analyzed: July 23, 2015

Sample Source/Location: Product / Faucet Date Reported: July 25, 2015

Page: 1 of 1

SAMPLE CODE	PARAMETERS	RESULT	STANDARD SPECIFICATION PNS DW 2007	REMARKS
MIC-15718	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	0	<500	

Test Method Used: Multiple Tube Fermentation, SMEW 22nd Ed. 2012

Note: "Results relate to samples as received"

Analyzed by:

IRENE D. SALONGA, RMT
Analyst
PRC Reg #: 0008432

Noted by:

HELEN P. SUBRADIL, RChe
Laboratory Head
PRC Reg #: 0013823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry.
Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.




Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.

Accreditation Number: 06-051-14-LW-2

Jalandoni Estate, Lapuz Iloilo City

email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15719

Name of Customer: DUMALAG WATER DISTRICT

Address: Brgy. Dolores, Dumalag, Capiz

Sample Description: Clear / Without Sediment

Time of Sampling: 08:16 PM

Sample Source/Location: Product / Faucet

Date Sample Submitted: July 23, 2015

Date Sample Analyzed: July 23, 2015

Date Reported: July 25, 2015

Page: 1 of 1

SAMPLE CODE	PARAMETERS	RESULT	STANDARD SPECIFICATION PNS DW 2007	REMARKS
MIC-15719	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	0	<500	

Test Method Used: Multiple Tube Fermentation, SMEW 22nd Ed. 2012

Note: "Results relate to samples as received"

Analyzed by:

IRENE D. SALONGA, RMT
Analyst
PRC Reg #: 0008432

Noted by:

HELEN P. SUBRADIL, RChe
Laboratory Head
PRC Reg #: 0013823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry. Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.



Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.

Accreditation Number: 06-051-14-LW-2

Jalandoni Estate, Lapuz Iloilo City

email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15782

Name of Customer: DUMALAG WATER DISTRICT (SITIO AYUYAN)

Address: Dumalag, Capiz

Sample Description: Clear / Without Sediment

Date Sample Submitted: August 6, 2015

Time of Sampling: 12:00 NN

Date Sample Analyzed: August 6, 2015

Sample Source/Location: Product/Faucet

Date Reported: August 8, 2015

Page:


1 of 1

SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15782	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	0	


Test Method Used: Multiple Tube Fermentation, SMEW 22nd Ed. 2012

Note: "Results relate to samples as received"

Analyzed by:


IRENE D. SALONGA, RMT
Analyst
PRC Reg #: 0008432

Noted by:


HELEN P. SUBRADIL, RChE
Laboratory Head
PRC Reg #: 0013823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry.

Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.



Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.
Accreditation Number: 06-051-14-LW-2
Jalandoni Estate, Lapuz Iloilo City
email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15783

Name of Customer: **DUMALAG WATER DISTRICT (DOLORES)**

Address: Dumalag, Capiz

Sample Description: Clear / Without Sediment

Time of Sampling: 12:00 NN

Sample Source/Location: Product/Faucet

Date Sample Submitted: August 6, 2015

Date Sample Analyzed: August 6, 2015

Date Reported: August 8, 2015

Page: 1 of 1

SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15783	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	1	

Test Method Used: Multiple Tube Fermentation, SMEW 22nd Ed. 2012
Note: "Results relate to samples as received"

Analyzed by:

IRENE D. SALONGA, RMT
Analyst
PRC Reg #: 0008432

Noted by:

HELEN P. SUBRADIL, RChE
Laboratory Head
PRC Reg #: 0013823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry. Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.




Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.

Accreditation Number: 06-051-14-LW-2

Jalandoni Estate, Lapuz Iloilo City

email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15958

Name of Customer: **DUMALAG WATER DISTRICT (DOLORES)**

Address: Dumalag, Capiz

Sample Description: Clear / Without Sediment

Time of Sampling: 06:30AM

Sample Source/Location: Product/Faucet

Date Submitted: September 03, 2015

Date Analyzed: September 03, 2015

Date Reported: September 07, 2015

Page : 1 of 1

SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15958	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	1	

Test Method Used: Multiple Tube Fermentation, SMEW 22nd Ed. 2012

Note: "Results relate to samples as received"

Analyzed by:

JERRILA A. MEDIANA, MIB
Analyst

Noted by:

HELEN P. SUBRADIL, RChE
Laboratory Head
PRC Reg #: 0013823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry.

Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.




Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.

Accreditation Number: 06-051-14-LW-2

Jalandoni Estate, Lapuz Iloilo City

email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15-1129B

Name of Customer: **DUMALAG WATER DISTRICT (SITIO AYUYAN)**


Address: Dumalag, Capiz
Sample Description: Clear / Without Sediment
Time of Sampling: 05:00 PM
Sample Source/Location: Product/Faucet

Date Submitted: October 10, 2015
Date Analyzed: October 10, 2015
Date Reported: October 15, 2015
Page: 2 of 2

SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15-1129B	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	2	

Test Method Used: Multiple Tube Fermentation, SMEWW 22nd Ed. 2012
Note: "Results relate to samples as received"

Analyzed by:


ROXANNE E. JAGOLINA, RMT

Analyst


PRC Reg #: 65737

Reviewed by:


JERRICA A. MEDIANA, MIB

Microbiologist

Approved by:


HELEN P. SUBRADIL, RChE

Laboratory Head

PRC Reg #: 13823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry. Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.




Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.

Accreditation Number: 06-051-14-LW-2

Jalandoni Estate, Lapuz Iloilo City

email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15-1129A

Name of Customer: **DUMALAG WATER DISTRICT (DOLORES)**

Address: Dumalag, Capiz

Sample Description: Clear / Without Sediment

Time of Sampling: 05:00 P.M.

Sample Source/Location: Product/Faucet

Date Submitted: October 10, 2015

Date Analyzed: October 10, 2015

Date Reported: October 15, 2015

Page: 1 of 2

SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15-1129A	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	0	

Test Method Used: Multiple Tube Fermentation, SMEWW 22nd Ed. 2012

Note: "Results relate to samples as received"

Analyzed by:

ROXANNE E. JAGOLINA, RMT

Analyst

PRC Reg #: 65737

Reviewed by:

JERRICA A. MEDIANA, MIB

Microbiologist

Approved by:

HELEN P. SUBRADIL, RChE

Laboratory Head

PRC Reg #: 13823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry. Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.




Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.

Accreditation Number: 06-051-14-LW-2

Jalandoni Estate, Lapuz Iloilo City

email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15-1288B

Name of Customer: **DUMALAG WATER DISTRICT (SITIO AYUYAN)**

Address: Dumalag, Capiz

Sample Description: Clear / Without Sediment

Time of Sampling: 04:20 PM

Sample Source/Location: Product/Faucet

Date Submitted: November 12, 2015

Date Analyzed: November 13, 2015

Date Reported: November 18, 2015

Page: 2 of 2

SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15-1288B	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	6	

Test Method Used: Multiple Tube Fermentation, SMEWW 22nd Ed. 2012


Note: "Results relate to samples as received"

Analyzed by:



ROXANNE E. JAGOLINA, RMT
Analyst

PRC Reg #: 65737

Reviewed by:


JERRICA A. MEDIANA, MIB
Microbiologist

Approved by:


HELEN P. SUBRADIL, RChe
Laboratory Head
PRC Reg #: 13823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry.

Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.




Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.

Accreditation Number: 06-051-14-LW-2

Jalandoni Estate, Lapuz Iloilo City

email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15-1288A

Name of Customer: DUMALAG WATER DISTRICT (DOLORES)

Address: Dumalag, Capiz

Sample Description: Clear / Without Sediment

Time of Sampling: 04:20 P.M.

Sample Source/Location: Product/Faucet

Date Submitted: November 12, 2015

Date Analyzed: November 13, 2015

Date Reported: November 18, 2015


Page: 1 of 2

SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15-1288A	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	5	


Test Method Used: Multiple Tube Fermentation, SMEWW 22nd Ed. 2012

Note: "Results relate to samples as received"


Analyzed by:


ROXANNE E. JAGOLINA, RMT
Analyst
PRC Reg #: 65737

Reviewed by:


JERRICA A. MEDIANA, MIB
Microbiologist

Approved by:


HELEN P. SUBRADIL, RChe
Laboratory Head
PRC Reg #: 13823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.


Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry.

Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.



Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.
Accreditation Number: 06-051-14-LW-2
Jalandoni Estate, Lapuz Iloilo City
email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15-1364

Name of Customer: **DUMALAG WATER DISTRICT**

Address: Dumalag, Capiz

Sample Description: Clear / Without Sediment

Time of Sampling: 05:30 A.M.

Sample Source/Location: Product/Faucet

Date Submitted: December 03, 2015

Date Analyzed: December 03, 2015


Date Reported: December 08, 2015

Page: 1 of 1


SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15-1364	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	9	

Test Method Used: Multiple Tube Fermentation, SMEW 22nd Ed. 2012
Note: "Results relate to samples as received"


Analyzed by:


ROXANNE E. JAGOLINA, RMT
Analyst
PRC Reg #: 65737

Reviewed by:


LAIKA E. SUAREZ, RMT
Analyst
PRC Reg #: 0070389

Approved by:


HELEN P. SUBRADIL, RChE
Laboratory Head
PRC Reg #: 13823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.


About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry.
Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.



Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.
Accreditation Number: 06-051-14-LW-2
Jalandoni Estate, Lapuz Iloilo City
email add: astslabiloilo@yahoo.com



TEST REPORT

Bacteriological Examination of Water

TR NO.: MIC-15-1411B

Name of Customer: **DUMALAG WATER DISTRICT (SITIO ANGEL)**

Address: Dumalag, Capiz

Sample Description: Clear / Without Sediment

Time of Sampling: 04:20 PM

Sample Source/Location: Product/Faucet

Date Submitted: December 11, 2015

Date Analyzed: December 11, 2015

Date Reported: December 16, 2015

Page: 2 of 2

SAMPLE CODE	PARAMETERS	STANDARD SPECIFICATION PNS DW 2007	RESULT	REMARKS
MIC-15-1411B	TOTAL COLIFORM (MPN / 100mL)	<1.1	<1.1	PASSED
	FECAL COLIFORM (MPN / 100mL)	<1.1	<1.1	
	HPC (CFU / mL)	<500	14	

Test Method Used: Multiple Tube Fermentation, SMEWW 22nd Ed. 2012

Note: "Results relate to samples as received"

Analyzed by:

Roxanne E. Jagolina
ROXANNE E. JAGOLINA, RMT

Analyst

PRC Reg #: 65737

Reviewed by:

Laika E. Suarez
LAIKA E. SUAREZ, RMT

Analyst

PRC Reg #: 0070389

Approved by:

Helen P. Subradil
HELEN P. SUBRADIL, RChe

Laboratory Head

PRC Reg #: 13823

*This test report shall not be reproduced except in full without the written approval of the laboratory.

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry.

Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.



Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.
Jalandoni Estate, Lapuz Iloilo City
email add: astslabiloilo@yahoo.com
contact no.: 033- 5014269, 09173058082

Certificate of Analysis

TR NO.: CHEM-15219

Name of Customer: **DUMALAG WATER DISTRICT**
Address: **Dumalag, Capiz**
Sample Description: **Clear/ No Sediment**
Time of Sampling: **6:45 a.m**
Sample Source/Location: **Product**


Date Sample Submitted: **September 3, 2015**
Date Sample Analyzed: **September 3, 2015**
Date Reported: **September 10, 2015**

TEST PERFORMED	METHOD	RESULTS	ACCEPTABLE VALUES	REMARKS
Color (Apparent color)	Colometric Method	1	10 color units	PASSED
Total dissolved solids (mg/L)	Gravimetric Method, dried @ 180° C	83.70	500 <10 for product that undergone osmosis / distillation process	PASSED
Electrical Conductivity (us/cm)	Electrical Conductivity Meter	285		
Turbidity	Turbidimetry	0.48	5 NTU	PASSED
pH	Glass Electrode Method	7.52	6.5 – 8.5 5 – 7 for product water undergone reverse osmosis	PASSED
Chloride (ppm)	Argentometric Method	9	250 ppm	PASSED
Total Hardness	Titrimetric Method	138.14	300 as CaCO ₃	PASSED
Calcium (ppm)		132.13		
Magnesium (ppm)		6.01		
Iron (ppm)	Phenanthroline Method	nil	1.0 ppm	PASSED
Nitrate (ppm)	Spectrophotometric Method	nil	50 pmm	PASSED
Nitrite (ppm)	Diazotization Method	0.429	3 ppm	PASSED
Odor	Threshold Odor Test (Sensory Evaluation Technique)	No odor detected	No objectionable odor	PASSED

References: Standard Methods for the Examination of Water and Waste Water 21st Edition 2005
Philippine National Standards for Drinking Water 2007

Note: 1. "Results relate to samples as received"
2. Test done is sub-contracted to NPCC-ADL (DOH ACCREDITATION #: 06-007-127LW-2)

Certified Correct:


HELEN P. SUBRADIL, RChE
Laboratory Head

**This test report shall not be reproduced except in full without the written approval of the laboratory.*

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry. Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.



Analytical Solution and Technical Services Iloilo, Inc.

Analytical Solutions & Technical Services, Iloilo Inc.
Jalandoni Estate, Lapuz Iloilo City
email add: astslabiloilo@yahoo.com
contact no.: 033- 5014269, 09173058082

Certificate of Analysis

TR NO.: CHEM-15428

Name of Customer: **DUMALAG WATER DISTRICT**
Address: **Dumalag, Capiz**
Sample Description: **Clear/ No Sediment**
Time of Sampling: **04:30 P.M**
Sample Source/Location: **Product/Faucet**


Date Sample Submitted: **December 11, 2015**
Date Sample Analyzed: **December 11, 2015**
Date Reported: **December 21, 2015**

TEST PERFORMED	METHOD	RESULTS	ACCEPTABLE VALUES	REMARKS
Color (Apparent color)	Colometric Method	1	10 color units	PASSED
Total dissolved solids (mg/L)	Gravimetric Method, dried @ 180° C	78.20	500 <10 for product that undergone osmosis / distillation process	PASSED
Electrical Conductivity (us/cm)	Electrical Conductivity Meter	269		
Turbidity	Turbidimetry	0.46	5 NTU	PASSED
pH	Glass Electrode Method	6.95	6.5 – 8.5 5 – 7 for product water undergone reverse osmosis	PASSED
Chloride (mg/L)	Argentometric Method	8.0	250 mg/L	PASSED
Total Hardness	Titrimetric Method	122.12	300 as CaCO ₃	PASSED
Calcium (mg/L)		116.12		
Magnesium (mg/L)		6		
Iron (mg/L)	Phenanthroline Method	nil	1.0 mg/L	PASSED
Nitrate (mg/L)	Spectrophotometric Method	nil	50 mg/L	PASSED
Nitrite (mg/L)	Diazotization Method	nil	3 mg/L	PASSED
Sulfates (mg/L)	Turbidimetric Method	nil	250 mg/L	PASSED
Odor	Threshold Odor Test (Sensory Evaluation Technique)	No odor detected	No objectionable odor	PASSED

References: Standard Methods for the Examination of Water and Waste Water 21st Edition 2005
Philippine National Standards for Drinking Water 2007

Note: 1. "Results relate to samples as received"
2. Test done is sub-contracted to NPCC-ADL (DOH ACCREDITATION #: 06-007-127LW-2)

Certified Correct:


HELEN P. SUBRADIL, RChE
Laboratory Head

**This test report shall not be reproduced except in full without the written approval of the laboratory.*

We deliver TRUST that you can count on.

About ASTS Analytical Solutions and Technical Services Iloilo, Inc.

Our Company is mainly engage with Laboratory services in Microbiological and Chemical testing. We also conduct Seminar, Workshops and Training on ISO / IEC 17025 Laboratory Internal Audit, Proficiency Testing, Quality Assurance / Quality Control in Analytical Laboratory, Laboratory Test Methods Development and Validation, GLP and GMP, Measurement of Uncertainty in Chemistry and Microbiology and Equipment Calibration and Maintenance. We are also involved in organizing awareness seminars on regulations relevant to Analytical Laboratory analysis and Agro- industrial Operations as an effort to support the Philippine Industry.
Our Laboratories are based in Jalandoni Estate Lapuz Iloilo and General Santos City, Philippines.